



m0490006
Task ID# 7438
cc: April

Application for Bond Release

| | |
|---|--|
| Operator/Permittee: Interpace Holdings LLC | |
| Mine/Project Name: Clinton Clay Pit | Permit ID#: M/49/0006 |
| | Permitted Acres: 57 |
| Reason for Bond Release: Vegetation Liability period complete on 34 acres | |
| Amount of Existing Surety: \$37,500 | |
| Amount of Surety requested for release: \$19,389 | |
| Partial Release of a <u>portion</u> * of the mine site: Acres Regraded: Specify Area: | Partial Release of <u>entire</u> mine site: (Backfilling and grading are completed) Acres: |
| Full Release of a <u>portion</u> * of the mine site: Acres to be released: Specify Area: 34 see map | Full Release of <u>entire</u> mine site: (Vegetation is established and has survived three growing seasons.) Acres to be released: |
| *For a bond release on a portion of the mine site, submit an updated map removing the released area from the disturbed or bonded area. | |

RECEIVED E-Mail

JUN 28 2016



Application for Bond Release

Reclamation practices must be completed in accordance with R647-2-109, or R647-3-109, or R647-4-111 as applicable.

| | |
|---|---|
| Have any shafts and tunnels been permanently sealed? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| Disposal of debris & other materials incident to mining | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| Public safety notifications such as posted signs or fences/barriers above high walls | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| Drainages, reestablished & stable | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Structures demolished and deleterious materials disposed of | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Erosion Controlled | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Slopes, waste piles, fills regraded | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Highwalls stabilized to an angle of 45° or less | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Meets Post mining Land Use (Indicate Land use) | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Roads and/or pads have been reclaimed | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Dams, Impoundments, Ditches, Pits reclaimed | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Topsoil redistributed – amendments added | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Vegetation meets 70% of the pre-mining cover? | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| <p><i>Note: For Final Bond Release vegetation must meets 70% of premining cover and has survived three years for or has survived one year growing season to maintain small mine status.</i></p> | |
| Plugging of boreholes | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| <p>If Answer is Yes, please fill out page 3 of this form</p> <p>DESCRIPTION of RECLAMATION ACTIVITIES COMPLETED</p> <p>(Describe any variance(s) that have been granted, date activity completed)</p> | |

